Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2014-P-00438

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513				
Exit Meeting Contact: Jett Dallas	Total Man Days: 1				
Pipeline Safety Representative(s): Charles Gribbins					
Company Representative to Receive Report: Michael Fuller	Emailed Date:				
Company Representative's Email Address: mfuller2@ameren.com	11/18/2014				

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Mount Vernon	Charles Gribbins	Mt. Vernon/Centralia	1	11/14/2014	Jett Dallas

Statement of Activities

On November 14, 2014, Staff conducted a Field Audit to determine compliance with applicable IL Adm. Codes and Code of Federal Regulations adopted via IL Adm. Part 590. The audit included field verification of the distribution system, Regulator Stations, and associated Fire Valves in the Mount Vernon Service area. See the attached checklist for information related to the Field Audit.

Exit Statement

<u>INSPECTION FINDINGS</u>

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2014-P-00438

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]